

SUBJECT: VL1000™ Luminaire Software Update	SERIES: 1000
DISTRIBUTION: Service Centers, End Users	STATUS: Routine

Introduction

VL1000™ SV 9/16/03

Software update **9/16/03** for VL1000™ luminaires is now available. This technical bulletin covers all changes in this new version.

For instructions on downloading and installing VARI***LITE** luminaire software, refer to technical bulletin LSW-002.

If you have any questions regarding this release or your VARI***LITE** product, please contact Vari-Lite Customer Service at 1-877-VARILITE.


Release Notes

Improvements

SV 9/16/03

VL1000 Luminaires

- Prevents erratic dimming control when used with VL1000 incandescent luminaires which contain the IGBT (on-board) dimmer.



IGBT (On-Board) Dimmer