

SUBJECT: VL1000™ Luminaire Software Update	SERIES: 1000
DISTRIBUTION: Service Centers, End Users	STATUS: Routine

## Introduction

---

### Embedded Software Update

Software update **02/17/04** for VL1000™ luminaires is now available. This technical bulletin covers all changes in this new version.

For instructions on downloading and installing VARI\*LITE® luminaire software, refer to technical bulletin LSW-002.

If you have any questions regarding this release or your VARI\*LITE product, please contact Vari-Lite Customer Service at 1-877-VARILITE.

## Release Notes

---

### Improvements in New Version

Series VL1000 Luminaires

- Improve reliability of fixture hours reset mode